



F16. 1



F16. 2






FIG. 4




FIG. 5




FIG. 6





FIG. 7






FIG. 9A




FIG. 9B




FIG. 10

				60 /					
70a				70ь ф			70c		
0.32	0.45	0.11	0.34	0.56	0.76	0.87	0.24	0.09	
0.22	0.10	0.07	0.41	0.48	0.80	0.77	0.44	0.26	
0.03	0.16	0.37	0.46	0.68	0.69	0.75	0.21	0.02	
.0.21	0.34	0.24	0.56	0.87	0.51	0.48	0.11	0.14	
0.26	0.22	0.19	0.27	0.38	0.23	0.31	0.12	0.25	
0.01	0.08	0.18	0.15	0.18	0.21	0.12	0.20	0.21	

FIG. 11




FIG. 12




FIG. 13A




FIG. 13B




FIG. 14